


Drilling:-



It is a process of creating hole.


⇒ Hole produced by any drill will be slightly smaller than size some margin is kept for Reaming operation.

⇒ Reaming:- is a process of exacting the hole ~~reaming~~

⇒ In twist drill there will be some unbalance masses due to which it's body may rub the finish part. To avoid this rubbing drill body is slightly tapered

Boring:- It is the process enlarging the hole primarily by single point cutting tool. Multiple cutting point tools are also available.


Trepanning:- Gundrill





In trepanning process material is removed only from the periphery and the central portion rises inside the tube it is meant to produce large diameter hole.

very deep hole are produced by Gum drills. There is hole at centre

through which we pumping cutting fluid in machining area. It not only take heat from machining area but also helps the chip to flow in backward direction



Broaching:- Broach is a multipoint cutting tool in which cutting edge are increasing in diameter. When the broach pulled through a hole we get mirror like surface finish.
(used for Super finishing)





Blind hole.

Counter ~~milling~~ Boring:- It's a process of increasing the diameter of hole by end milling process and it is a ~~sitting~~ ^{Seating} place for bolts and nuts




Counter Sinking:- It's a process of making the ^{hole} slightly taper at the entry by sinking tool or tool of slightly larger in diameter the purpose it is ~~sitting~~ ^{Seating} place screw heads.





β - point angle.




$$\frac{d/2}{w} = \sin \beta$$

width of chip

$$w = \frac{d/2}{\sin \beta}$$

$$\frac{f_t}{f/2} = \sin \beta \Rightarrow f_1 = t_1 = \frac{f}{2} \sin \beta$$

uncut chip thickness



$\frac{f}{2}$ = effective feed

Point angle in the drill is having effect similar to SCEA in single point cutting tool.


As it can be seen in the analysis that smaller is the point angle chips will be thinner and wider.

⇒ while machining Ductile material since it produce continuous chip, if the chips are thick it will accumulate in helix due to work hardening. So for machining ductile material we use smaller point angle because thinner chip will easily come out through helix.

Helix Angle

* At the centre of drill since cutting edge merge to the chisel edge rake angle will be zero. As we are moving towards periphery rake angle will gradually increase and after ~~per~~ periphery since cutting edge merge into helix so rake angle will exactly equal to helix angle.

Feed Angle (γ)



$$\tan \gamma = \frac{f}{2\pi r}$$

Clearance Angle

Ductile

Brittle

Clearance 8-12

6-9

Point angle 118°

135°

Flute:- through which chips going out


Feed Angle:-

Work piece material that is going from the back side of cutting edge form an angle with the horizontal plane called feed angle.

This material will be removed by the next cutting edge in next half revolution. Due to this feed angle work material will

try to hit the cutting edge and try to break it. So clearance is provided on the tool to avoid this rubbing. ϕ

For machining ductile material since there will be elastic recovery so large clearance has to be provide to the tool.



$$\text{Helix angle} + \text{Lip Angle} + \text{Lip relief angle} = 90^\circ$$


CHAP-6

work book

Q.3 $f = 3.9 \text{ mm/min}$
 $P = 6 \text{ mm}$

$$V = \frac{3900}{6} = 650 \text{ rpm}$$

Q4




$$\frac{d/2}{x} = \tan 60^\circ \Rightarrow x = \frac{5}{\tan 60^\circ} = 2.8$$

$$l = x + 20 + 2$$

$$l = 22 + 2.8 = 24.8 \text{ mm}$$

$$\text{No. of rev.} = \frac{l}{\text{feed}} = \frac{24.8}{0.2} \text{ rev}$$

$$\text{time} = \frac{24.8 \times 60}{0.2 \times 300} = 25 \text{ sec.}$$

Q.13

$$\frac{d/2}{x} = \tan 59^\circ$$

$$x = \frac{7.5}{\tan 59^\circ} = 4.50 \text{ mm}$$

$$l = \cancel{1.664} + 50 + 2 + 2 = 58.50 \text{ mm.}$$

$$\text{No. of rev.} = \frac{l}{f} = \frac{58.50}{0.2} = 292.5 \text{ rev.}$$

$$T = \frac{278.3 \times 60}{500} = \cancel{33.39} \text{ sec.}$$


$$35.10 \text{ sec}$$

* If point angle Not give.

1. Calculate without Considering x
2. or Consider $x = 0.3d$ and Calculate

Q.19

$$L = 50 + \frac{5}{\tan 60^\circ} = 52.88 \text{ mm}$$



$$\text{No. of rev.} = \frac{52.88}{0.2} = 264.433$$

$$\text{time} = \frac{264.433}{600} = 0.4407 \text{ min}$$

Q.20

Half the diameter is depth of cut

$$d/2 = 10 \text{ mm}$$

Q.21

$$L = 45 \text{ mm}$$

$$d = 15 \text{ mm}$$

$$V = 20 \text{ m/min}$$

for 1 hole

$$V = \pi D N$$

$$20 = \pi \times 15 \times N$$

$$T_1 = \frac{45}{0.2 \times 424.62} = 0.529 \text{ min}$$

$$N = 424.62 \text{ rpm}$$

~~Q.22~~ T_1 - machining for 1 hole

$$(i) \eta = \frac{\text{tool life}}{T_1} = \frac{100}{0.529} = 189 \text{ hrs}$$

$$(ii) \text{ Production} = \frac{1}{T_1 + \text{idle time}}$$

$$P.R. = \frac{1}{T_1 + \text{idle time}} = \frac{1}{0.853} = 1.16$$

$$P.R. = \frac{1}{0.529 + \frac{20}{60}}$$

$$\begin{aligned} \text{Production time} &= T_1 + \text{idle time} \\ &= 0.529 + \frac{20}{60} \\ &= 0.853 \text{ min} \end{aligned}$$

Q.22

$$L = 30 + 3 + 2 + \frac{10}{\tan 60^\circ} = 40.77 \text{ mm}$$


$$\frac{f}{2} = 0.01 \text{ mm/rev} \quad f = 0.02 \text{ mm/rev}$$

$$\text{No. of rev.} = \frac{40.77}{0.02} = 2038.5$$

$$\text{So } T = \frac{2038.5 \times 60}{500} = 244.62 \text{ sec}$$

Chap 19Q. 14

$$G.R. = \frac{\text{w.p. material}}{\text{tool material wear}}$$



$$\delta = \pi D \times t \times w_1$$

$$G.R. = \frac{2.5 \times 200 \times 5}{\pi (300) (20 \times 10^{-3}) (25)} = 5.30$$

Q. 15

$$\text{Specific energy} \times MRR = \text{Energy (fcv)}$$

$$\frac{40 \times 22 \times 0.04 \times 1180}{60} = f_c V = f_c \times \pi \times \frac{220}{60} \times \frac{3600}{1000}$$

$$f_c = 16.7 \text{ N}$$

CHAP 4 ①

$$d_1 = 6.25 \text{ mm}$$

$$V = 18 \text{ m/min}$$

$$d_2 = 25 \text{ mm}$$

$$V_1 = \pi d_1 N_1$$

$$N_1 = \frac{18000}{6.25 \times \pi}$$

$$V_2 = \pi d_2 N_2$$

$$N_2 = \frac{18000}{25 \times \pi}$$

$$\gamma = \left(\frac{N_2}{N_1} \right)^{1/5} = \left(\frac{25}{6.25} \right)^{1/5} = 1.319$$

③

$$L \sin \left(\frac{\alpha}{2} \right)$$

$$= 400 \sin 2^\circ$$

Q.4

$d_1 = 30 \text{ mm}$


$d_2 = 40 \text{ mm}$

$V = 30 \text{ m/min}$

$f = 0.01 \text{ cm/rev}$

$f = 0.1 \text{ mm/rev}$

$N = \frac{3000 V}{\pi D}$



① $d_1 = 2 \text{ mm}$

$30 \rightarrow 34 \quad d_m = 32 \text{ mm}$

$l = 100 \text{ mm}$

$N_1 = \frac{30000}{3.14 \times 32}$

No. of rev = $\frac{100}{0.1} = 1000 \text{ rev.}$

$N_1 = 2988.5 \text{ rpm}$

$T_1 = \frac{1000}{2988.5} = 33.50 \text{ min}$

② $d_2 = 2 \text{ mm}$

$34 - 38 \quad d_m = 36 \text{ mm} \quad N_2 = \frac{30000}{3.14 \times 36}$

$T_2 = \frac{1000}{26.53}$

$N_2 = 26.53$

$T_2 = 37.69$

③ $d_3 = 1 \text{ mm}$

$38 - 40 \quad d_m = 39 \text{ mm}$

$N_3 = \frac{30000}{3.14 \times 39}$

$N_3 = 244.977$

$T_3 = \frac{1000}{244.977} = 4.082$

$T = 3.35 + 3.76 + 4.08$
 $= 11.19$

Q.5

$d = 10 \text{ mm}, 20 \text{ mm}$

Dia of Hole = 20 mm

$V = 10 \text{ m/min}$

$f = 0.2 \text{ mm/rev.}$

① No. of rev = $\frac{50}{0.2} = 250 \text{ rev}$

$N_1 = \frac{10,000}{3.14 \times 10} = 318.47 \text{ rpm}$

$T_1 = \frac{250}{318.47} = 0.785 \text{ min}$

② $N_2 = \frac{10,000}{3.14 \times 20} = 159.235$

$T_2 = \frac{250}{159.235} = 1.56$

$T = 1.56 + 0.785$

$T = 2.4 \text{ min}$

Q.6

$$d = 100 \text{ mm} \quad N = 500 \text{ rpm}$$

$$\text{No. of chatter} = \frac{360}{30} = 12 \text{ chatter.}$$

$$P = \frac{500}{60} \times 12 = 100 \text{ Hz}$$

Q.8

$$V = 50 \text{ m/min}$$



$$f = 0.8 \text{ mm/rev.}$$

$$d = 1.5 \text{ mm}$$

$$\text{MRR} = f d V$$

$$= 50 \times 10^3 \times 1.5 \times 0.8 \text{ mm}^3/\text{min}$$

$$\text{MRR} = 60000 \text{ mm}^3/\text{min}$$

Q.7

$$\tan \frac{\alpha}{2} = \frac{7.5}{55} \Rightarrow \alpha = 7.76^\circ$$

$$2\alpha = 15.53^\circ$$

$$\text{Offset} = L \sin \frac{\alpha}{2} = 90 \sin 7.76^\circ = 12.16 \text{ mm}$$

Q.8

$$\text{double start} = 2 \times 2$$

$$= 4 \text{ mm/rev}$$

Q.10

39

$$P = 10 \text{ kW}$$

$$d = 40 \text{ mm}$$



$$V = 0.35 \text{ m/min}$$

$$L = 50 \text{ mm}$$

$$f_z = 0.01 \text{ mm/tooth}$$

$$\phi 40 \rightarrow \phi 48$$

Broach



$$\text{No. of Cutting} = \frac{L}{f_z} = \frac{50}{0.01} = 5000$$

$$L = 50 + 15 (399) = 10000 \text{ mm}$$

$$T = \frac{6035}{0.35 \times 1000} = 0.172 \text{ min}$$

Q.11

$$V = 20 \text{ m/min}$$

$$f = 1.2 \text{ mm/rev.}$$

$$60 \text{ mm} \rightarrow 42 \text{ mm}$$

$$\textcircled{1} d_1 = 3 \text{ mm}$$

$$60 \rightarrow 54 \text{ } d_m = 57 \text{ mm}$$

$$N_1 = \frac{20,000}{3.14 \times 57} \text{ rpm}$$

$$N_1 = 111.687 \text{ rpm}$$

$$T = 11.68 \text{ min}$$

$$L = \frac{215}{1.2} = 179.166$$

$$T_1 = 1.604 \text{ min}$$

$$\textcircled{12} d = 3 \text{ cm}$$

$$\text{No. of turn} = \frac{3}{45} = 45 \text{ turn}$$

$$L = 15 + 0.57 \times 0.5 = 16 \text{ cm}$$

$$1 \text{ rev} \rightarrow 3 \text{ cm}$$

$$16 \text{ cm} \rightarrow 48 \text{ rev}$$

$$T_m = \frac{48}{88} \times 7$$

$$\textcircled{2} d_1 = 3 \text{ mm}$$

$$54 - 48$$

$$d_m = 51 \text{ mm}$$

$$N_2 = \frac{20,000}{3.14 \times 51}$$

$$N_2 = 124.827 \text{ rpm}$$

$$T_2 = \frac{115}{1.2 \times 124.827}$$

$$T_2 = 0.767 \text{ min}$$

$$T = 3.048 \text{ min}$$

$$\textcircled{3} d_3 = 3 \text{ mm}$$

$$48 - 42$$

$$d_m = 45 \text{ mm}$$

$$N_3 = \frac{20000}{3.14 \times 45}$$

$$N_3 = 141.47 \text{ rpm}$$

$$T_3 = \frac{115}{1.2 \times 141.47}$$

$$T_3 = 0.677$$

Q. 13

$$4 \text{ cm} \rightarrow 3.5 \text{ cm}$$

$$V = 30 \text{ m/min}$$

$$f = 0.4 \text{ mm}$$

$$d_m = 3.75 \text{ cm}$$

$$d_m = 37.5 \text{ mm}$$

$$N = \frac{30,000}{37.5 \times 3.14}$$

$$N = 254.647 \text{ rpm}$$

$$L = 15 \text{ cm}$$

$$L = 150 \text{ mm}$$

$$\text{No. of rev} = \frac{150}{0.4} = 375 \text{ rev.}$$

$$T = \frac{375}{254.647} = 1.472 \text{ min}$$

Q. 14

$$\phi = 50 \text{ mm} - 42 \text{ mm}$$

$$\textcircled{1} d_1 = 3 \text{ mm}$$

$$50 - 44$$

$$d_m = 47 \text{ mm}$$

$$N = 450 \text{ rpm}$$

$$\text{No. of rev} = \frac{50 + 3}{0.2} = 265 \text{ mm}$$

$$t_1 = \frac{265}{450} = 0.588$$

$$\textcircled{2} d_1 = 1$$

$$44 \rightarrow 42$$

$$d_m = 41 \text{ mm}$$

$$N = 450$$

$$\text{No. of rev} = \frac{53}{0.2} = 265$$

$$t_2 = \frac{265}{450} = 0.588$$

$$T = 1.176$$

Q. 15

$$52 \rightarrow 44 \text{ mm}$$

$$\textcircled{1} d_1 = 3 \text{ mm}$$

$$52 - 46$$

$$d_m = 49 \text{ mm}$$

$$N = \frac{35000}{\pi \times 49} = 227.364 \text{ rpm}$$

$$L = 200 \text{ mm}$$

$$\text{No. of rev} = \frac{200}{0.3} = 666.67 \text{ rev}$$

$$T = \frac{666.67}{227.364} = 2.932 \text{ min}$$

② $d = 1 \text{ mm}$

$46 \rightarrow 44$

$d_m = 45 \text{ mm}$

$N_2 = \frac{50000}{\pi \times 45}$

$N_2 = 353.67$


$L = \frac{200}{0.1} = 2000$

$T_2 = \frac{2000}{353.67}$

$T_2 = 5.654$

$T = 8.58 \text{ min}$

Q.16



$\tan \theta = \frac{5}{45}$

$\theta = 6.340^\circ$

Back rake angle = $10 - 6.340 = 3.66^\circ$

Clearance = $10 + 6.34 = 16.34^\circ$

Q.17

$d = 4.5 \text{ mm}$


Rise = $0.0125 \times 8 = 0.1 \text{ mm}$

Rise needed = $4.5 - 0.1 = 4.4$

no. of rough feeds = $\frac{4.4}{0.1} = 44$

length = $(22 \times 43) + (8 \times 20) + (4 \times 20)$

$L = 1186.0$



Chap 5

0.3

Double Stroke mean backward & forward 30 per min

One double stroke = 2 sec.

t_1 = forward time

t_2 = return time

$$t_2 < t_1$$

$$\frac{t_2}{t_1} = 0.6$$

$$L = 250 \text{ mm}$$

$$t_1 + t_2 = 2 \text{ sec}$$


$$1.6 t_1 = 2$$

$$t_1 = \frac{2}{1.6} = 1.25 \text{ sec.}$$

$$t_2 = 0.75 \text{ sec.}$$

$$V = \frac{L}{t_1} \text{ Cutter velocity} = \frac{250 \times 10^{-3} \times 60}{1.25} = 12 \text{ m/min}$$

1.4



$$V = 8 \text{ m/min} \quad f = 0.3 \text{ mm/stroke}$$

$$\frac{t_1}{t_2} = \frac{1}{2}$$

$$\text{No of stroke} = \frac{30}{0.3} = 100$$


$$l = 640 \text{ mm}$$

$$t_1 = \frac{l}{V} = \frac{640}{8 \times 1000} = 0.08 \text{ min}$$

$$t_2 = 0.04 \text{ min}$$

$$t = 0.12 \text{ min for 1 stroke}$$

$$\text{for 100 stroke} = 100 \times 0.12 = 12 \text{ min}$$

Q.6

$$V = 13.5 \text{ m/min}$$

$$f = 0.57 \text{ mm/d.s}$$

$$t_2/t_1 = 0.83$$

$$t = t_1 + t_2$$

$$t = 1.83 t_1$$

$$t = 1.83 \times 3.056$$

$$t = 5.593 \text{ min}$$

$$Q = 240$$

$$\text{No. of strokes} = \frac{98}{0.57}$$

$$t_2 = \frac{98 \times \frac{240}{0.57}}{13.5 \times 1000}$$

$$t_2 = 3.056$$

$$t_1 = \frac{240}{13.5}$$

Q.7

$$\frac{\text{Power}}{\text{Sp energy}} = 1.49 \text{ J/mm}^3 \times \text{MRR}$$

$$\text{Power, sp en} = 1.49 \times 200 \times 4 \times 0.25$$

$$= 298 \text{ watt}$$

Q.8

$$t_1/t_2 = 3/2$$

$$L = 200 \text{ mm}$$

$$V = 18 \text{ m/min}$$

$$t_1 = \frac{200}{18} \times 60 = \frac{2}{3} \text{ sec.}$$

$$t_2 = \frac{2/3}{3/2} = \frac{4}{9} \text{ sec}$$

$$t = t_1 + t_2 = \frac{2}{3} + \frac{4}{9} = \frac{10}{9} \text{ sec} = \frac{10}{9 \times 60} = \frac{1}{54} \text{ min}$$

$$\text{rpm} = 54 \text{ rpm}$$

Q.9

$$f = 0.001 \text{ mm}$$

44

$$\frac{t_1}{t_2} = \frac{2}{1}$$

$$t_1 + t_2 = 40$$

$$t_1 = \frac{20}{3} \text{ min}$$

$$t_1 = \frac{0.150 \times \cancel{60000}}{v} = \frac{20}{3} \times 60$$

$$\frac{150,000}{v} = \frac{20 \times 60}{3}$$

$$t = \frac{10 \times 60}{10^5}$$

$$\text{no. of stroke} = \frac{100}{0.001} = 10^5$$

$$t = t_1 + t_2$$

$$\frac{10 \times 60}{10^5} = \frac{0.15}{v} + \frac{0.15}{2v}$$

$$v = 37.5 \text{ m/sec}$$

Shaping & Planing : (single point Cutting tool)

shaping is a machining operation for Generating Flat surface.

shaping - work piece is stationary & cutting tool is given a reciprocating motion

Planing :- it is similar to shaping & diff is that workpiece is reciprocating instead of cutting tool.

* In shaping time for forward stroke is more because in forward motion we require more force to remove material so it is a slow stroke in backward stroke no force require so it is fast

$$t_1 > t_2$$

Plane stress $k' = \frac{\sigma_0}{2}$

Plane strain $\rightarrow \dot{\epsilon}_2 = 0 \rightarrow k' = \frac{\sigma}{\sqrt{3}}$

$\hookrightarrow$ No metal flow during forging

eg. forging of cylindrical billet stress

$$\sigma_1 - \sigma_2 = 2k'$$

Q.2 Book
P.g. 331

Brittle material

$\downarrow$

Fracture mechanism

$$k_c = y \sigma \sqrt{\pi a}$$

$$\sigma = 300 \text{ MPa}$$

$$k_c = 3.6 \text{ MPa} \sqrt{\text{m}}$$

$$y = 1$$

$$a = ?$$

k_c - Fracture toughness

y - material.

σ - strength

a - max' crack size

Surface Crack
 $a \rightarrow a/2$

Q.10

P.g. 20

$$L = 200 \text{ mm}$$

$$t = 2 \text{ sec.}$$

$$\frac{t_2}{t_1} = \frac{2}{3}$$

$$t_1 + t_2 = 2$$

$$t_1 + \frac{2}{3} t_1 = 2 \Rightarrow \frac{5t_1}{3} = 2 \Rightarrow t_1 = \frac{6}{5} \text{ sec}$$

$$V = \frac{L}{t_1} = \frac{200 \text{ mm} \times 5 \times 60}{\frac{6}{5} \times 1000} = 10 \text{ m/min}$$

Q.11

$$L = 750 \text{ mm}$$

$$\frac{t_2}{t_1} = \frac{1}{4}$$

$$f = 3 \text{ mm}$$

$$V_1 = 9 \text{ m/min}$$

$$\text{No. of stroke} = \frac{90}{3} = 30 \text{ stroke.}$$

$$V_1 = \frac{L}{t_1} \quad \text{for 1 stroke}$$

$$\text{for 30 stroke} \quad t_1 = \frac{750}{9000} \times 30 \Rightarrow t_1 = 2.5$$

$$t_2 = 0.625$$

$$t = 3.125 \text{ min}$$

Q.12

$$L = 2000 \text{ mm}$$

$$W = 310 \text{ mm}$$

$$\text{No. of Stroke} = 310$$

$$\checkmark t_1 = \frac{2}{1} = 2 \text{ sec.}$$

$$\checkmark t_2 = 1 \text{ sec.}$$

$$t = 3 \text{ sec.}$$

$$\text{total time} = 930 \text{ sec}$$

$$\text{total time} = 930 \text{ sec.}$$

$$\text{for one work} = \frac{930}{2}$$

$$= 465 \text{ sec.}$$



Q. 13

$$b = L = 150 \text{ mm}$$

$$\frac{t_2}{t_1} = 0.7$$

$$V_1 = 20 \text{ m/min}$$

$$f = 0.3 \text{ mm/stroke}$$

$$\text{No. of stroke} = \frac{1500}{0.3} = \cancel{5000 \text{ stroke}} \quad 333.33 \text{ stroke}$$

$$V_1 = \frac{L}{t_1}$$

$$\Rightarrow 20 \times 1000 = \frac{150}{t_1} \times 333.33$$

$$\cancel{t_1} = \frac{20,000}{\cancel{50000}} = \frac{2}{5} \text{ min}$$

$$t_2 = t_1 = \frac{5}{2}$$

$$t_2 = 1.75$$

$$t_1 + t_2 = 4.25 \text{ min}$$

$$\text{MRR} = A_c \times f \times d$$